## (PIONEER

## SERVICE MANUAL

### HIGH-POLYMER STEREO HEADPHONES

# SE-700

#### 1. SPECIFICATIONS




#### CAUTION:

More than 30 minutes's exposure of a high polymer diaphragm used in the SE-700 will affect its property, resulting in impairing the tone quality.

Also never touch the diaphragm directly with the fingers but it will go ineffective. With these things in mind, be careful when disassembling the SE-700 for replacement of the cord, for example.

(ARS-077-0)

### 2. EXPLODED VIEW AND PARTS LIST



### 3. 3-P PLUG WITH CORD REPLACEMENT




Fig. 1

Wrench ring A with a screwdriver. Once the hermetically-sealed ring A has been wrenched, it will become uneven and scratched. Therefore, replacement with a new ring will be required.




Fig. 2

Loosen two screws. There is no need to remove them.





Fig. 3

Remove all four screws and take out of the case.


Then remove three sheets of polyurethane. When putting them back again, follow the order of sheets F, B, C, as shown in Fig. 3.

Downloaded from <a href="www.Manualslib.com">www.Manualslib.com</a> manuals search engine



Remove the diaphragm, with care taken never to touch it. Remeber that even light touching will render the diaphragm ineffective.

Be sure not to expose the diaphragm for more than 30 minutes.



Unsolder three points with a soldering iron as shown in Fig. 5

Clip cord metal stopper and pull out the cord.

Key No.	Descriptions	Part No.	
1	Name plate (L)	SAL-452-0	
2	Nut M3		
3	Band holder A	SNK-156-0	
4	Slaider	SNK-159-0	
5	Steel ball 4ø		
6	Head band A	SNB-104-0	
7	Band holder B	SNK-157-0	
8	Plate spring	SNB-108-0	
9	⊕ Panhead screw M3 x 8		
10	Head pad	SCD-494-0	
11	Name plate (R)	SAL-453-0	
12	Headphone unit assembly (R)	SXC-110-0	
12-1*	Head band B	SNB-105-0	
12-2	Ear pad	SCD-485-0	
12-3	Adhesive tape	SEH-001-0	
12-4*	Band stopper pin	SNB-109-0	
12-5*	Shaft	SNK-160-0	
12-5	Shart	31117-100-0	
12-6*	Bass (R)	SNK-155-0	
12-7*	Punching net	SNB-116-0	
12-8*	Packing B	SEB-025-0	
12-10*	Terminal	SKF-032-0	
12-11*	⊕ panhead screw M2.6 x 4		
12-12*	Acoustic material F	SEF-182-0	
12-13*	Acoustic material B	SEC-179-A	
12-14*	Acoustic material C	SEC-179-B	
12-15	Stopper	SNB-114-0	
12-16*	Case	SNK-161-0	
12-17*	Metal ring B	SNB-103-0	
12-18*	Mesh cover	SNB-111-0	
12-19*	Net	SCD-487-0	
12-20*	⊕ panhead screw M3 x 6	002 107 0	
13	Metal ring A	SNB-102-0	
14	Headphone unit assembly (L)	SXC-109-0	
14-1	Cord stopper	SNB-113-0	
14-2*	Bass (L)	SNK-154-0	
14-2	Rubber bush		
14-3	Cord with 3-P plug	SNK-158-0 SKM-017-0	
	Peaking acco		
	Packing case	SHG-107-0	
	Packing inner case	SCC-241-0	
	Operating instructions	SRB-092-0	

#### PIONEER ELECTRONIC CORPCRATION

4-1, 1-Chome, Meguro, Meguro-ku, Tokyo 153, Japan

U.S. PIONEER ELECTRONICS CORPORATION

75 Oxford Drive, Moonachie, New Jersey 07074,U.S.A.

PIONEER ELECTRONIC (EUROPE) N.V.

Meir-Center Meir 21, 2000 Antwerp, Belgium

PIONEER ELECTRONICS AUSTRALIA PTY. LTD.

256-8 City Road, South Melbourne, Victoria 3205, Australia

AUGST. 1974 Printed in Japan

## SERVICE BULLETIN

No. S-75002

Service Department, International Division

LIST OF PARTS CHANGED FOR FACTORY MODIFICATION

DATE May.12.1975

Subject: Headphone unit assemblies have been changed.

Reason: Improvement of reliability and sound quality.

Parts Number		Parts Name or Description		* Disposition	
Former	New	Former ( Remove )	New (Add)	of Former Parts	
SXC-109	SXC-120	Headphone unit asse	nbly (L)	С	
SXC-110	SXC-121	řt.	(R)	С	

<sup>\*</sup>Disposition of former parts marked as A, B and C means;

A: Discard.

B: Available for other model. So, please keep it.

C: Available only for model of before modification. So, please keep it.

D: Available after minor improvement. So, please keep it.

Application				Ref. of S. Manual	
Mode1	Unit or Ass'y No.	Serial No.	Month	Page	Position
SE-700	-	_	April'75	1,2	Key No.12,14
	A LATER CO.				


Notice: Please alter the service margials in accordance with the above table.

Please turn over

(

#### Explanation:

To distinguish the difference between the old and the new one, "A" is marked on the base of headphone unit assembly as shown below.



The former and new headphone unit assemblies are not interchangeable. So, Please do not use both the old and the new type together.